
## **Appendix D**

**HISTORICAL FLOODING** 





Upstream of Kentisbeare



Bridge Adjacent to Brook House





Fore Street Bridge (Downstream Face)



Bridge House, looking upstream, flood boards in photo were ineffective as water gained entry at side and front of the property






Ken Brook – Garage



## Goodiford Farm






Goodiford Farm – Flood water overtopped the footbridge





Road Adjacent to Sheepwash Mill





Glimsters Farm



Glimsters Farm (Internal)





Channel Adjacent to Glimsters Farm



Brook House





Brook House, the road in the foreground is the preferential route for excess flows



Bridge House





## 2 Bridge Cottages

